


CERTIFIED TO:
NESTOR DIAZ

1. None Provided at Time of Survey.
2. Visible Encroachments Shown if Any.
3. Not a Survey Matter.
4. Not on a State Owned Body of Water.
5. Not a Survey Matter.
6. Not a Survey Matter.
7. Not a Survey Matter.
8. Parcel Affected as Shown Hereon.
9. Not a Survey Matter.
10. Not a Survey Matter.
11. Parcel Affected as Shown Hereon.
12. Parcel Affected as Shown Hereon.
13. Parcel Affected as Shown Hereon.
14. Parcel Affected. (Blanket For Ingress/Egress to/through parcels). Access highlighted as Shown Hereon



<u>C1</u>	<u>C2</u>	<u>C3</u>
R=425.00'(P)	R=425.00'(P)	R=425.00'(P)
Delta=14°53'07"(P)	Delta=15°13'33"(P)	Delta=30°53'18"(P)
L=110.41'(P)	L=112.94'(P)	L=229.12'(P)
Chord Bearing=	Chord Bearing=	Chord Bearing=
S 38°35'18" E 110.10'(P)	S 53°38'38" E 112.61'(P)	S 15°42'06" E 226.36'(P)
S 38°31'18" E 109.88'(M)	S 53°40'28" E 112.64'(M)	S 15°41'17" E 226.56'(M)

[illegible]